

SELF BREAKING EMULSION LOW FOAMING ALKALINE CLEANER

This low foaming cleaner may be used under high pressure and at elevated temperatures to remove grease, oils and fats which will rapidly separate in the effluent without pH adjustment.

<u>COMPOUND</u>	<u>% WT</u>
Water	68.00
Hampene 100 (Hampshire)	2.00
Soda ash	10.00
COLA™ FAX 3373 PE	9.00
COLA™ TERIC ZF-50	7.00
Dowanol DPM	4.00
Total	100.00

PROCEDURE:

To the water add ingredients in the order listed with good agitation. Make sure each product is solubilized before adding next product.

Formula 197

Last Modified 07/5/2005

WARRANTY

Colonial Chemical guarantees that its products meet published specifications. No other warranties or guarantees are expressed or implied because the use of this material is beyond the control of Colonial Chemical.