

# LOW FOAM SPRAY WASH

---

## FORMULA

<u>COMPOUND</u>	<u>%</u>
Water	72.00
KOH-45	10.00
COLONIAL DF-20	8.00
Versene 100	5.00
Surfonic LF017	<u>5.00</u>
TOTAL	100.00

Appearance: Clear thin liquid

5% pH: 13.8

5% cloud point: 45°C

5% Draves wetting time: < 1 sec.

Blend in order given with sufficient stirring to clarify.

Use at 4 oz. – 8 oz. per gallon.

# HARD SURFACE DEGREASER

---

<u>COMPOUND</u>	<u>%</u>
Water	71.00
KOH-45	8.00
COLONIAL DF-20	6.00
TKPP	10.00
Anhydrous Metasilicate	3.00
Versene 100	<u>2.00</u>
TOTAL	100.00

Appearance: Clear thin liquid

5% pH: 13.8

5% cloud point: 58° C

5% Draves wetting time: 13 sec/

Blend in order given with sufficient stirring to clarify.

Use at 4 oz. – 8 oz. per gallon.

Formula 218

Last Modified 07/5/2005

### WARRANTY

Colonial Chemical guarantees that its products meet published specifications. No other warranties or guarantees are expressed or implied because the use of this material is beyond the control of Colonial Chemical.